






SUNROOM SETBACK DETAILS

ADDRESS	1880 GLENHURST DRIVE SNELLVILLE, GA 30078
PROJECT	RENOVATION OF THE CURRENT SUNROOM ALONG WITH THE ADDITION OF AN EXTENSION TO IT
AREA	CURRENT SUNROOM - 156 SQFT EXTENSION - 148 SQFT TOTAL - 304 SQFT



SUNROOM RENOVATION PROJECT


ADDRESS	1880 GLENHURST DRIVE SNELLVILLE, GA 30078
PROJECT	RENOVATION OF THE CURRENT SUNROOM ALONG WITH THE ADDITION OF AN EXTENSION TO IT
AREA	CURRENT SUNROOM - 156 SQFT EXTENSION - 148 SQFT TOTAL - 304 SQFT



Current Sunroom



Improper roofing causes water to flow in reverse, resulting in leaks and necessitating renovations



ADDRESS	1880 GLENHURST DRIVE SNELLVILLE, GA 30078
---------	--